

FIG. 1





FIG. 1



112V

DRIVE MOTOR

The diagram shows a circular disk with concentric tracks. A vertical line 124 and a horizontal line 126 intersect at the center, dividing the disk into four quadrants. The top and bottom quadrants are labeled 'N' (North), and the left and right quadrants are labeled 'S' (South). The tracks are labeled with numbers: 100, 122, 128, 130, 180, 182, and 184. Arrows indicate the direction of magnetic flux or data flow. The outermost track is labeled 100. The tracks are numbered in increments of 2, starting from 100 and ending at 184. The disk is shown in a cross-sectional view, with the tracks appearing as concentric circles. The disk is divided into four quadrants by a vertical line 124 and a horizontal line 126. The quadrants are labeled N (North) and S (South). The tracks are labeled 100, 122, 128, 130, 180, 182, and 184. Arrows indicate the direction of magnetic flux or data flow.

FIG. 4




FIG. 5A




FIG. 5B




FIG. 6




FIG. 7